Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight *DHR Id#:* **046-5064**

Resource Identification

Property Name(s): ..... House {}
Property Date: ..... ca 1910
Address(s): ..... 13208 Old Suffolk Road {Current}
County/Independent City: Isle Of Wight
City: .....
State, Zip: .....Virginia
USGS Quad Name: ..... WINDSOR
Surrounding area: ..... Rural

National Register Eligibility Status
Property is Historic (50 years or older)

Property has been recommended Not Eligible for listing

Resource Description

Ownership Status: ..... Private

Primary Resource Exterior Componant Description:

Component	Comp Type/Form	Material	Material Treatment
Chimneys	Chimneys - Central interior	Brick	Chimneys - Common Bond
Foundation	Foundation - Piers	Brick	Foundation - Common Bond
Porch	Porch - 1-story	Wood	Porch - Post, Square
Roof	Roof - Gable	Metal	Roof - Standing Seam
Structural System	Structural System - Frame	Wood	Structural System - Weatherboard
Windows	Windows - Double-hung	Wood	Windows - 2/2

Site Description: ..... This house is located in a rural area. The owner just recently passed away and the son is the new owner. The son plans to demolish the house. He owns the Windsor Woodworking Company to the west of this house.

Secondary Resource Desc: There are eight outbuildings associated with this house.

WUZIT Count:

No.	Wuzit Types	Historic?
1	House	Historic
1	Garage	Historic
3	Shed	Historic
2	Equipment Shed	Historic
1	Barn	Historic
1	Quonset Hut	Non-historic

NR Resource Count:

Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight ***DHR Id#:*** **046-5064**

Individual Resource Information

WUZIT: ..... Quonset Hut

Est. Date of Construction:	1980 ca {Site Visit}	*Accessed?*	No
Primary Resource?	No	*Number of Stories:*	1.0
Architectural Style:	Other	*Condition:*	Good
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion

Description: The metal quonset hut is located to the east of the house.

WUZIT: ..... Equipment Shed

Est. Date of Construction:	1930 ca {Site Visit}	*Accessed?*	No
Primary Resource?	No	*Number of Stories:*	1.0
Architectural Style:	Other	*Condition:*	Good
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion

Description: The equipment shed (B) is an open structure with a gabled roof.

WUZIT: ..... Barn

Est. Date of Construction:	1930 ca {Site Visit}	*Accessed?*	No
Primary Resource?	No	*Number of Stories:*	1.0
Architectural Style:	Other	*Condition:*	Fair
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion

Description: The barn features a wood paneled exterior and gabled roof covered in standing-seam metal.

WUZIT: ..... Shed

Est. Date of Construction:	1930 ca {Site Visit}	*Accessed?*	No
Primary Resource?	No	*Number of Stories:*	1.0
Architectural Style:	Other	*Condition:*	Good
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion

Description: Southeast of the house are two sheds (B&C), both clad in weatherboard with gabled roofs

WUZIT: ..... Shed

Est. Date of Construction:	1930 ca {Site Visit}	*Accessed?*	No
Primary Resource?	No	*Number of Stories:*	1.0
Architectural Style:	Other	*Condition:*	Fair
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion

Description: Southeast of the house are two sheds (B&C), both clad in weatherboard with gabled roofs.

WUZIT: ..... Equipment Shed

Est. Date of Construction:	1930 ca {Site Visit}	*Accessed?*	No
Primary Resource?	No	*Number of Stories:*	1.0
Architectural Style:	Other	*Condition:*	Good
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion

Description: To the northeast is a shed (A), Quonset hut, and equipment shed (A). The shed and equipment shed both display gabled roofs covered in standing-seam metal.

Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight ***DHR Id#:*** **046-5064**

WUZIT: ..... Shed

Est. Date of Construction:	1930 ca {Site Visit}	*Accessed?*	No
Primary Resource?	No	*Number of Stories:*	1.0
Architectural Style:	Other	*Condition:*	Good
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion

Description: To the northeast is a shed (A), Quonset hut, and equipment shed (A). The shed and equipment shed both display gabled roofs covered in standing-seam metal.

WUZIT: ..... Garage

Est. Date of Construction:	1950 ca {Owner/site visit}	*Accessed?*	No
Primary Resource?	No	*Number of Stories:*	1.0
Architectural Style:	Other	*Condition:*	Good
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion

Description: Eight outbuildings are associated with this house. West of the house is a garage covered in corrugated acrylic with a gabled roof clad in standing-seam metal.

WUZIT: ..... House

Est. Date of Construction:	1910 ca {Owner/site visit}	*Accessed?*	No
Primary Resource?	Yes	*Number of Stories:*	1.0
Architectural Style:	Other	*Condition:*	Good
Interior Plan Type:		*Threats to Resource:*	Transportation Expansion

Description: Built ca. 1910, this one-story Frame Vernacular style house features a wooden frame structural system that rests on brick piers. The exterior of this house is covered in weatherboard and the front-gabled roof is clad in standing-seam metal. Fenestration consists of two-over-two wooden double-hung sash windows. The front porch wraps around the north and east sides of the house and features a hipped roof with square wooden supports. A brick chimney is situated on the central interior portion of the roof and two flues are located on the south and west additions to the house. Two gabled additions have been appended to the south elevation and shed-roofed additions have been appended to the south, southwest, and west elevations of the house.

Cemetery Information

Bridge Information

National Register Eligibility Information *(Intensive Level Survey)*

Historic Context(s): ..... Domestic

Historic Time Period(s): ..... P- Reconstruction and Growth (1865 to 1914)

Significance Statement: Though this house is currently in good condition, its design is common for the period of construction. This resource has no apparent association with any event or person important in our nation's history, lacks architectural significance, and does not appear to have the ability to yield important information. The architectural integrity of this house has been diminished due to numerous additions and the alteration of the front porch. The resource is recommended as not eligible for the NRHP under Criteria A, B, C, or D.

Bibliographic Documentation

Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight ***DHR Id#:*** **046-5064**

Reference #: 1
Bibliographic RecordType: ..... Survey
Author: ..... CCR, Inc.
Citation Abbreviation: .....
Notes: ..... VDHR # 2002-1760
VDOT # 0460-969-101, PE-101
Architectural Survey, Route 460
Corridor Study

Ownership Information

Graphic Media Documentation

Medium	*Depository ID #*	*Photo Depository*	*Date*	*File Name*
35mm B&W	11	VDHR	2004/07/01	Farm Complex

Cultural Resource Management (CRM) Events

CRM Event # 1,
Cultural Resource Management Event: ..... Phase I Survey
Date: 2004/08/31
Organization or Person: ..... CCR, Inc.
VDHR Project ID # Associated with Event: .. 2002-1760
CRM Event Notes or Comments: ..... VDHR # 2002-1760
VDOT # 0460-969-101, PE-101
Architectural Survey, Route 460
Corridor Study

CRM Event # 2,
Cultural Resource Management Event: ..... DHR Staff: Not Eligible
Date: 2004/11/18
Organization or Person: .....
VDHR Project ID # Associated with Event: . 2002-1760
CRM Event Notes or Comments: .....